

Owners Corporation Plan 2470
Committee Report
February 2010

- Birch removal and replacement
- Flooding in U10 & U12
- Insurance claims
 - U12 - glass in door
 - U12, U10 damage through water ingress from storm
 - U2 storm damage to door
 - U5 water leaking from U6 above (into 2010)
- Repairs to paving in driveway
- Repairs to clothesline (line to be replaced)
- Northside tea-tree screen fence
- Northside damp damage to garage wall 8 Power Ave. (into 2010)
- Website maintenance